

HIGH-LINE MFG.
ROCK-MASTER PICKERS

# HIGH-LINE MFG. ROCK-MASTER PICKERS

ROCK-MASTER A NEW NAME IN THE ROCK PICKING FIELD, IS MANUFACTURED BY HIGH-LINE MFG. INC. A COMPANY MANNED WITH A CREW WHICH HAS OVER 25 YEARS EXPERIENCE IN THE INDUSTRY.

THIS OPERATOR MANUAL HAS BEEN PREPARED TO PROVIDE INFORMATION NECESSARY FOR THE SAFE AND EFFICIENT OPERATION OF YOUR ROCK-MASTER PICKER, IN IT YOU WILL FIND SAFETY PROCEDURES, MAINTENANCE ROUTINES AND DETAILED PARTS DIAGRAMS.

IF YOU SHOULD FIND THAT YOU REQUIRE INFORMATION NOT COVERED IN THIS MANUAL, FEEL FREE TO CONSULT US OR YOUR LOCAL DEALER.

SHOULD THE NEED ARISE, THIS MANUAL WILL ASSIST YOU IN ACQUIRING REPLACEMENT PARTS. SHOULD YOUR DEALER NOT HAVE THE PARTS YOU REQUIRE IN STOCK, HE WILL BE HAPPY TO ORDER THEM FOR YOU.

THE ROCK-MASTER ROCK PICKER WAS DESIGNED TO WORK IN THE MOST DIFFICULT OF ROCK PICKING SITUATIONS. A LITTLE TIME AND EFFORT SPENT IN PROPER MAINTENANCE WILL INCREASE THE PERFORMANCE AND DURABILITY OF YOUR PICKER.

IN ORDER TO MAINTAIN HIGH EFFICIENCY STANDARDS, CHANGES OR IMPROVMENTS ARE MADE FROM TIME TO TIME. HIGH-LINE MFG. INC. RESERVES THE RIGHT TO MAKE THOSE CHANGES AND ADD IMPROVMENTS WHEN PRACTICAL TO DO SO WITHOUT INCURRING ANY OBILATION TO MAKE SUCH CHANGES AND IMPROVEMENTS ON MACHINES SOLD PREVIOUSLY.

HIGH-LINE MFG. INC. THANK YOU AND CONGRATULATE YOU FOR DELECTING A ROCK-MASTER ROCK PICKER AS THE MACHINE OF YOUR CHOICE.

RAYMOND BUSSIERE PRESIDENT



### TABLE OF CONTENTS

| TABLE OF CONTENTS   |
|---------------------|
| SCOPE               |
| WARRANTY4           |
| HITCH               |
| APRON6              |
| RIGHT SIDE VIEW7    |
| LEFT SIDE VIEW8     |
| H614 HUB9           |
| HYDRAULIC LAYOUT10  |
| 3" x 30" HYD. CYL11 |
| 3" x 10" HYD. CYL12 |

 YOUR MODEL R-500 ROCK-MASTER STONE PICKER WAS DESIGNED FOR EASE OF HANDLING IN THE TOUGHEST OF CONDITIONS.

THE R-500 WILL CLEAN YOUR FIELDS OF LARGE STONES FAST AND WITH THE GREATEST OF EASE.

THE ROCK-MASTER STONE PICKER IS NOT A LUXURY, IT IS A SOUND ADDITION TO YOUR FARMING OPERATION.

MANY ACRES OF TROUBLE FREE SERVICE CAN BE EXPECTED WITH A LITTLE INSIGHT AND PROPER MAINTENANCE DESCRIBED IN THIS MANUAL.

DIAGRAMS AND PARTS LISTS HAVE BEEN INCLUDED FOR YOUR CONVENIENCE TO ASSIST IN THE ADJUSTMENTS AND UPKEEP THAT MAY BE REQUIRED.

# WARRANTY

HIGH-LINE MFG. INC. warrants its products to the original owner for a period of two years from date of purchase. Subject to the following provisions.

\*1st YEAR - PARTS & LABOUR \*2nd YEAR - PARTS ONLY

\*All matters related with the warranty of products must be handled through an authorized ROCK-MASTER dealer.

\*Any labour subject to warranty must be authorized by a HIGH-LINE MFG. INC. representative, before work is started.


\*Machines used for rental, custom work or industrial/construction use, will be warranted for a period of 6 months from date of purchase. Parts & labour.


\*Warranty will be void if any component of rock-picker is altered or modified in any way, unless written permission is given by HIGH-LINE MFG. INC.

\*HIGH-LINE MFG. INC. will not assume any responsibility for whatever damage may occur to equipment to which the rock-picker may be attached.


\*Warranty terms and conditions are subject to provincial and state legislation.










| NO. | PART NO. | DESCRIPTION               |
|-----|----------|---------------------------|
| 1   | 201001   | 3" x 10" HYD. CYL.        |
| 2   | 801044   | 5/8" x 10" UNC BOLT W/NUT |
| 3   | 502804   | APRON LIFT PIPE           |
| 4   | 500201   | PIPE CLAMP                |
| 5   | 801106   | 5/8" x 2" UNF BOLT W/NUT  |
| 6   | 801027   | 1" x 3½" UNC BOLT W/NUT   |
| 7   | 801104   | ½" x 3½" UNF BOLT W/NUT   |
| 8   | 502801   | APRON TINE                |
| 9   | 502802   | APRON LESS TINES          |
|     | 502803   | APRON COMPLETE W/TINES    |










| NO.        | PART NO.           | DESCRIPTION  |
|------------|--------------------|--|
| 1          | 301001             | DC15 DUST CAP  |
| 2          | 301002             | CASTELLATED NUT 1"- 14 UNS                           |
| 3          | 301003             | WAI7 WASHER I" I.D. $\times$ 2" 0.D.                 |
| 4          | 301004             | LM48510 OUTER CUP                                    |
| 5          | 301005             | LM48548 OUTER CONE                                   |
| 6          | 301006             | WB12 WHEEL BOLT $9/16$ " = 18 UNF x $1\frac{1}{2}$ " |
| 7          | 301007             | H614 HUB   |
| 8          | 301008             | SE16 SPINDLE ONLY                                    |
| 9          | 30100 <del>9</del> | LM603012 INNER CUP                                   |
| 10         | 301010             | LM603049 INNER CONE                                  |
| 1 <b>1</b> | 301011             | SE16 GREASE SEAL                                     |









| NO. | PART NO. | DESCRIPTION             |
|-----|----------|-------------------------|
| 1   | 501601   | HOOK ONLY               |
| 2   | 801212   | 2" x 14" PIN            |
| 3   | 801032   | 1 ½" × 6 UNC BOLT W/NUT |
| 4   | 206001   | 6" x 10" HYD. CYL.      |
| 5   | 801213   | 2" x 12" PIN            |
| 6   | 501603   | 8" U-CLAMP              |
| 7   | 501602   | ROCK GUARD              |
| 8   | 501604   | 10" U-CLAMP             |
| 9   | 501605   | HOOK FRAME              |

#### ROUTINE MAINTENANCE

-PERIODICALLY CHECK AIR PRESSURE IN THE TIRES AS UNEQUAL PRESSURE WOULD MAKE IT PRACTICALLY IMPOSSIBLE TO LEVEL MACHINE PROPERLY.

- -CHECK WHEEL BOLTS FOR TIGHTNESS.
- -CHECK ALL BOLTS FOR TIGHTNESS.
- -CHECK HYD. HOSE & TUBING CONNECTIONS.
- -GREASE ALL PIPE CLAMPS DAILY.
- -CHECK CYLS, DAILY.

#### SPECIFICATIONS

| PICKING WIDTH      |
|--------------------|
| DUMP HEIGHT        |
| TIRES              |
| CYLINDERS3 x 30    |
| 3 x 10             |
| HYDRAULIC PRESSURE |
| MAX. HORSEPOWER100 |
| BUCKET CAPACITY    |
| WE!GHT             |

#### <u>DANGER</u>

ANY PETOLEUM PRODUCT UNDER PRESSURE CAN INFILTRATE THE SKIN CAUSING SERIOUS AFTER EFFECTS. IF THIS SHOULD HAPPEN, APPLY COLD PACKS TO THE AFFECTED AREA AND SEE A DOCTOR IMMEDIATELY.